

Introduction

Although Xilinx has made every effort to ensure the highest possible quality, these Virtex™-5 engineering samples (ES) are subject to the limitations described in the following errata.

Devices

These errata apply to the Virtex-5 devices, as shown in [Table 1](#).

Table 1: Virtex-5 Devices Affected by These Errata

Devices	XC5VLX30TCES	JTAG ID (Revision Code): 2, 3, 4, 5
	XC5VLX50TCES	JTAG ID (Revision Code): 2, 3, 4, 5
	XC5VLX110TCES	JTAG ID (Revision Code): 2, 4
	XC5VLX330TCES	JTAG ID (Revision Code): 0, 1
Packages	All	
Speed Grades	-1, -2	

Hardware Errata Details

This section provides a detailed description of each hardware issue known at the release time of this document.

Block RAM

Block RAM Synchronous FIFO Mode - LX30T, LX50T, and LX110T

F_{MAX_FIFO} is 400 MHz when using the attribute `EN_SYN = TRUE`.

Block RAM ECC Scrub Mode

ECC Scrub mode (`EN_ECC_SCRUB = TRUE`) is not supported and will not be supported in production devices.

OSERDES

Optional inversion for the divided clock (`CLKDIV`) in the OSERDES is not supported.

Configuration

When reconfiguring with a different bitstream on an already configured device, in rare cases a static LUT input can be inverted. For more information see answer record 24582.

Integrated Endpoint Block for PCI Express

6-Pin Reset Mode - LX30T and LX50T

The `CRMMACRSTN` and `CRMLINKRSTN` pins are not supported. The `RESETMODE` attribute must be set to `FALSE` which selects the 4-pin reset scheme described in [UG197: PCI Express Endpoint Block User Guide](#).

Users of the LogiCORE Endpoint Block Plus for PCI Express™ (v1.2.1 or later with EA patch) are not affected by this errata. The LogiCORE™ Endpoint Block for PCI Express™ (v1.1 or later) implements this workaround for LX50T devices by always setting `RESETMODE` to `FALSE`.

Unsupported Status Output Pins - LX30T and LX50T

The following status output pins are unsupported. They are used to indicate register values set by the Root Complex in the Configuration Space. For specific pin descriptions, refer to [UG197: PCI Express Endpoint Block User Guide](#).

- IOSPACEENABLE
- MEMSPACEENABLE
- BUSMASTERENABLE
- PARITYERRORRESPONSE
- SERREENABLE
- INTERRUPTDISABLE
- URREPORTINGENABLE
- MAXPAYLOADSIZE[2:0]
- MAXREADREQUESTSIZE[2:0]

Workaround

The register values can be read through the Management interface. Users of the LogiCORE Endpoint Block Plus for PCI Express (v1.2.1 or later with EA patch) are not affected by this errata. The information present in these signals is made available at the interface. The LogiCORE Endpoint Block for PCI Express (v1.1 or later) does not incorporate this workaround.

Management Interface - LX30T and LX50T

The Management read enable input pin MGMTRDEN must be tied High when the Management interface is used.

Workaround

Tie MGMTRDEN High. The LogiCORE Endpoint Block for PCI Express (v1.3 or later) implements this workaround. Users of the LogiCORE Endpoint Block Plus for PCI Express (v1.2.1 or later with EA patch) are not affected by this errata.

Configuration Space

Some configuration space register bits are incorrectly set, however, the functionality is not affected.

- The following bits are incorrectly set to 1 - LX30T, LX50T, and LX110T
 - The Data Link Layer Link Active Reporting Capable bit [20] of the Link Capabilities register
 - The Data Link Layer Link Active bit [13] of the Link Status Register
- For all devices listed in [Table 1](#) - LX30T, LX50T, LX110T, and LX330T
 - The Version field of the Power Management capability is incorrectly set to 010b

Error Reporting

Error Signaling Message Transaction Layer Packets are incorrectly sent for Ignored Messages, Unsupported Requests, and Poisoned TLPs.

Transaction Layer Interface

Gaps in user request receive data destination (LLKRXDSTREQN) cannot be longer than four cycles, unless the gaps are between packets.

Workaround

Prevent gaps in LLKRXDSTREQN of longer than four cycles. Users of the LogiCORE Endpoint Block Plus for PCI Express (v1.2.1 or later with EA patch) are not affected by this errata. Users of the LogiCORE Endpoint Block for PCI Express (v1.1 or later) must implement this work around.

LLKRXDSTREQN must be deasserted in the same cycle that LLKRXSRCCLASTREQN is asserted.

Workaround

Deassert LLKRXDSTREQN in the same cycle that LLKRXSRCCLASTREQN is asserted. The LogiCORE Endpoint Block Plus for PCI Express (v1.2.1 or later with EA patch) implements this workaround. This workaround is not incorporated in the LogiCORE Endpoint Block for PCI Express (v1.1 or later).

Transaction Ordering

The transaction ordering implemented by the Virtex-5 Integrated Endpoint block for PCI Express designs has the following differences from the PCI Express base specification, revision 1.1, Table 2-23.

- Completion packets can be blocked by non-posted packet requests.

Workaround

A user application waiting for a completion packet must drain the non-posted queue to ensure that the completion packet already in the Rx buffer can be drained. In addition, if a far-end device is waiting for a completion packet, the far-end device must free up non-posted flow control credits before the Integrated Endpoint block will transmit a completion packet waiting in its Tx buffer. This workaround is not incorporated in the LogiCORE Endpoint Block Plus for PCI Express (v1.2.1 or later with EA patch) or the LogiCORE Endpoint Block for PCI Express (v1.1 or later).

- Packets without flow control credits can sometimes be transmitted, when a link partner does not advertise infinite completion flow control credits and the endpoint is in an 8-lane configuration, causing flow control protocol errors.

Workaround

The user application must put posted packets in the transmit queue only if sufficient credits are available.

- Posted packets waiting for flow control credits in the transmit buffer can sometimes be passed by completion or non-posted packets. For example, a memory read packet could pass a memory write packet with overlapping addresses, resulting in incorrect data being read. After this violation occurs, transmission of completion packets and/or non-posted packets could be halted if the posted packet buffer becomes empty. Transmission of completion packets and/or non-posted packets in the buffer will resume once a new posted packet is transmitted

Workaround

The user application must put posted packets in the transmit queue only if sufficient credits are available.

GTP Transceivers

AC JTAG

AC JTAG mode is not supported and will not be supported in production devices.

GTP CRC Block - LX30T and LX50T

The initial state for the cyclic-redundancy-check (CRC) block, CRC64 and CRC32, cannot be changed from its default value of 32'hFFFFFFF.

GTP CRC Parallel Interface Timing

For proper timing, the parallel CRCIN interface must be clocked off of an inverted CRCCLK and sourced from a register clocked on the noninverted CRCCLK in the CLB fabric. The CRC CORE Generator™ Wizard generates wrapper files that include this circuitry. See Answer Record #24879 for more details.

GTP Transmit Interface Timing

For proper timing, the transmit interface must be clocked off of an inverted TXUSRCLK2 and sourced from a register clocked on the noninverted TXUSRCLK2 in the CLB fabric. The GTP CORE Generator Wizard generates wrapper files that include this circuitry.

RX Buffer Bypass (RX Low Latency Mode)

The receiver buffer bypass mode is only supported for 10-bit internal data paths with a receiver PLL divider of 1. Receiver PLL divider settings of 2 or 4 are not currently supported.

Reference Clock Input Resistance

The differential input resistance R_{IN} of the RocketIO GTP reference clock ranges from 160Ω to 180Ω. The higher resistance should not affect the performance of the GTP transceiver.

Operational Guidelines

Design Software Requirements

The devices covered by these errata, unless otherwise specified, require the following Xilinx development software installations.

- Speed specification v1.48 (or later) and Xilinx software ISE 8.2i SP3 (or later) is required when designing for the devices covered by this errata.
- The stepping should be set to ES in the constraint file (UCF file):
CONFIG STEPPING = "ES";
- A summary list of ISE software known issues pertaining to the Virtex-5 features is available at:
http://www.xilinx.com/xlnx/xil_ans_display.jsp?iCountryID=1&iLanguageID=1&getPagePath=23625

Notes and Recommendations

ESD Protection

For LX30T, LX50T, and LX110T:

- The V_{BATT} pin ESD protection meets HBM 500V.
- The MGTREFCLKN, MGTREFCLKP, and MGTVREF pins ESD protection meet HBM 250V and 100V CDM. Added care is recommended during handling.

For LX330T:

- The MGTREFCLKN, MGTREFCLKP, and MGTVREF pins ESD protection meet HBM 1000V and 150V CDM. Added care is recommended during handling.

Power Supply Requirements - LX30T, LX50T, and LX110T

During power-up and configuration, the V_{CCINT} supply requires a maximum current I_{CCINT} as shown in [Table 2](#).

Table 2: V_{CCINT} Power Supply Maximum Current Requirements

Device	V_{CCINT}	I_{CCINT}
XC5VLX30TCES	1.05V	2.5A
XC5VLX50TCES	1.05V	2.75A
XC5VLX110TCES	1.05V	4.00A

Traceability

The XC5VLX50TCES is marked as shown in Figure 1. The other devices listed in Table 1 are marked similarly.




Figure 1: Example XC5VLX50TCES Package Marking

Additional Questions or Clarifications

All other device functionality and timing meet the current data sheet specifications.

For additional questions regarding these errata, please contact your Xilinx Technical Support: <http://www.xilinx.com/support/clearxpress/websupport.htm> or your Xilinx Sales Representative: <http://www.xilinx.com/company/contact.htm>.

Obtaining the Most Recent Errata Version

If this document is printed or saved locally in electronic form, check for the most recent release, available to registered users on the Xilinx website at: http://www.xilinx.com/xlnx/xweb/xil_publications_index.jsp?category=Errata.

To receive an e-mail alert when this document changes, sign up at:

http://www.xilinx.com/xlnx/xil_ans_display.jsp?getPagePath=18815.

These errata apply to the following Virtex-5 documents:

Virtex-5 Overview (<http://www.xilinx.com/bvdocs/publications/ds100.pdf>)

Virtex-5 Data Sheet (<http://www.xilinx.com/bvdocs/publications/ds202.pdf>)

Virtex-5 User Guide (<http://www.xilinx.com/bvdocs/userguides/ug190.pdf>)

Virtex-5 XtremeDSP™ Design Considerations (<http://www.xilinx.com/bvdocs/userguides/ug193.pdf>)

Virtex-5 Configuration Guide (<http://www.xilinx.com/bvdocs/userguides/ug191.pdf>)

Virtex-5 Packaging and Pinout Specification (<http://www.xilinx.com/bvdocs/userguides/ug195.pdf>)

Virtex-5 RocketIO GTP Transceiver User Guide (<http://www.xilinx.com/bvdocs/userguides/ug196.pdf>)

Virtex-5 PCI Express Endpoint Block User Guide (<http://www.xilinx.com/bvdocs/userguides/ug197.pdf>)

Virtex-5 Embedded Tri-mode Ethernet MAC User Guide (<http://www.xilinx.com/bvdocs/userguides/ug194.pdf>)

Revision History

Date	Version	Description
11/17/06	1.0	Initial Xilinx release.
01/18/07	1.1	Added XC5VLX330TCES devices and speed grade - 2 to Table 1 and sections of the document. Revised the Integrated Endpoint Block for PCI Express errata. Revised RX Buffer Bypass section on page 3. Updated Figure 1 .
04/09/07	1.2	Added Configuration errata. Updated the GTP CRC Parallel Interface Timing section. Added device-specific information to ESD Protection and Power Supply Requirements - LX30T, LX50T, and LX110T sections.
06/08/07	1.3	Added Block RAM ECC Scrub Mode , OSERDES , and AC JTAG errata. Updated LogiCORE Endpoint Block Plus for PCI Express revision information.