

## Introduction

Thank you for participating in the Spartan®-6 FPGA Engineering Sample Program. As part of this program, we are pleased to provide to you engineering samples of the devices listed in [Table 1](#). Although Xilinx has made every effort to ensure the highest possible quality, these devices are subject to the limitations described in the following errata.

## Devices

These errata apply to the Spartan-6 devices shown in [Table 1](#).

*Table 1: Devices Affected by These Errata*

Devices	XC6SLX9 CES9951	JTAG ID (Revision Code): 0
	XC6SLX16 CES9951	JTAG ID (Revision Code): 3
	XC6SLX25 CES9951	JTAG ID (Revision Code): 0
	XC6SLX25T CES9951	JTAG ID (Revision Code): 0
	XC6SLX45 CES9951	JTAG ID (Revision Code): 3
	XC6SLX45T CES9951	JTAG ID (Revision Code): 3
	XC6SLX75 CES9951	JTAG ID (Revision Code): 0
	XC6SLX75T CES9951	JTAG ID (Revision Code): 0
	XC6SLX100 CES9951	JTAG ID (Revision Code): 0
	XC6SLX100T CES9951	JTAG ID (Revision Code): 0
	XC6SLX150 CES9951	JTAG ID (Revision Code): 3
	XC6SLX150T CES9951	JTAG ID (Revision Code): 3
Packages	All	
Speed Grades	-2, -3	

## Hardware Errata Details

This section provides a detailed description of each hardware issue known at the release time of this document.

### IODELAY2

In the devices listed in [Table 1](#), the IODELAY2 block can experience late data edge delays, early data edge delays, and single data bit corruption. MCB interfaces are not affected by the IODELAY2 errata.

#### ***Late Data Edge Delay in IDELAY and ODELAY Modes***

The IODELAY2 block can add up to 350 ps of delay on the rising or falling edge transitions when the IDELAY\_VALUE or ODELAY\_VALUE is 4 or higher for all IDELAY\_TYPE settings or when used as output delay. This behavior can be present at all data rates and should be included in system timing margin analysis.

### Early Data Edge Delay in ODELAY Mode

The IODELAY2 block used in the ODELAY mode can generate a data edge up to 350 ps early on the rising or falling edge transitions. This behavior can be present at data rates higher than 533 Mb/s and for all ODELAY\_VALUE settings and should be included in system timing margin analysis.

### Single Data Bit Corruption in IDELAY and ODELAY Modes

The IODELAY2 block can corrupt a single data bit for all IDELAY\_TYPE settings or when used in ODELAY mode.

#### Work-arounds

##### IDELAY\_TYPE=DEFAULT

The data rate must not exceed 250 Mb/s to avoid data corruption.

##### IDELAY\_TYPE=FIXED or VARIABLE\_FROM\_ZERO or When Used in ODELAY Mode

The IDELAY\_VALUE or ODELAY\_VALUE must not exceed the values in [Table 2](#) to avoid data corruption at the indicated data rate.

Table 2: Maximum IDELAY\_VALUE or ODELAY\_VALUE

Data Rate (Mb/s)	Bit Time (ps)	Maximum DELAY Value
1,050	952	7
1,000	1,000	8
945	1,058	9
800	1,250	14
667	1,499	20
625	1,600	22
533	1,876	28
400	2,500	43
333	3,003	54
266	3,759	72
200	5,000	101
188	5,319	107

##### IDELAY\_TYPE=VARIABLE\_FROM\_HALF\_MAX

The data rate must not exceed 400 Mb/s, the IODELAY2 IOCLK frequency must be equal to the data rate, and the positive increment must not exceed 5 to avoid data corruption.

##### IDELAY\_TYPE=DIFF\_PHASE\_DETECTOR

The data rate must not exceed 400 Mb/s and data to clock skew, including package trace difference, must not exceed 0.15 UI to avoid data corruption.

See [Answer Record 38408](#) for additional information.

## Memory Controller Block (MCB)

### MCB Not Supported

The memory controller block (MCB) is not supported in the devices listed in [Table 1](#).

## Block RAM

### **Dual Port Block RAM Address Overlap in READ\_FIRST and Simple Dual Port Mode**

When using the block RAM in True Dual Port (TDP) READ\_FIRST mode or Simple Dual Port (SDP) mode, with different clocks on ports A and B, the user must ensure certain addresses do not occur simultaneously on both ports when both ports are enabled and one port is being written to. Failure to observe this restriction can result in read and/or memory array corruption.

The description is found in the Conflict Avoidance section in v1.2 of [UG383](#), *Spartan-6 FPGA Block RAM Resources User Guide*.

This description was originally added to the *Spartan-6 FPGA Block RAM Resources User Guide*, v1.1, published 10/28/09. This errata is being provided to highlight this change and ensure that all users are aware of this design restriction. ISE® 12.1 software provides appropriate warnings for possible violations of these restrictions.

This issue will not be fixed in the devices listed in [Table 1](#).

#### **Work-around**

The recommended work-around to avoid memory array corruption issue is to configure the block RAM in WRITE\_FIRST mode. WRITE\_FIRST mode is available in block RAMs configured in TDP mode in all ISE software versions. WRITE\_FIRST mode is available in block RAMs configured in SDP mode from ISE v12.3 and later.

See [Answer Record 34533](#).

### **9K Simple Dual Port Block RAM Width Restriction**

The Spartan-6 FPGA RAMB8BWER in Simple Dual Port (SDP) mode (RAM\_MODE=SDP) only supports the 36-bit data width on both ports. Failure to set both ports to 36 bits (DATA\_WIDTH\_A=36, DATA\_WIDTH\_B=36) can result in data corruption.

The description is found in the Possible Configurations section in v1.2 of [UG383](#), *Spartan-6 FPGA Block RAM Resources User Guide*.

This description was originally added to the *Spartan-6 FPGA Block RAM Resources User Guide*, v1.2, published 02/23/10. This errata is being provided to highlight this change and ensure that all users are aware of this design restriction. ISE 12.1 software provides appropriate warnings for possible violations of these restrictions.

This issue will not be fixed in the devices listed in [Table 1](#).

#### **Work-around**

See [Answer Record 34541](#).

### **9K Block RAM Initialization**

Block RAM used in the 9K mode (RAMB8BWER) can fail to initialize user data or default values during configuration in the devices listed in [Table 1](#).

This issue will not be fixed in the devices listed in [Table 1](#).

#### **Work-arounds**

Either use 18K block RAM or write to the 9K block RAM to initialize it after configuration.

See [Answer Record 39999](#).

## Configuration

### ***BPI Configuration Not Supported in LX25/T Device***

Master BPI mode for configuration is not supported in the XC6SLX25 and XC6SLX25T devices listed in [Table 1](#). The other devices in [Table 1](#) that support Master BPI configuration are not affected.

See [Answer Record 36521](#) for additional information.

This issue will not be fixed in the XC6SLX25 and XC6SLX25T devices listed in [Table 1](#).

#### **Work-around**

Alternative configuration modes include Master SelectMAP mode with a Xilinx Platform Flash PROM or Master SPI mode, including x4 mode with a quad SPI Flash.

### ***16-Bit SelectMAP Configuration Maximum CCLK Frequency for LX100/T Devices***

The maximum CCLK configuration frequency has been revised from 40 MHz to 35 MHz for 16-bit-wide SelectMAP mode for the XC6SLX100/T devices listed in [Table 1](#). SelectMAP mode is also known as slave parallel or BPI mode. The parameters affected are  $F_{SMCCK}$  for slave mode (x16 only) and  $F_{MCCK}$  for master mode (SelectMAP/BPI x16 only). This change is included in [DS162](#), *Spartan-6 FPGA Data Sheet: DC and Switching Characteristics*, v1.10, November 4, 2010. All designs using 16-bit SelectMAP in the XC6SLX100/T devices should use a configuration frequency of less than 35 MHz. No software changes are associated with this revision.

See [Answer Record 38733](#) for additional information.

### ***Configuration Readback When Using 9K Block RAM***

Configuration readback can corrupt 9K block RAM (RAMB8BWER) data. Configuration readback (including iMPACT Verify) is not supported when 9K block RAM is used in the devices listed in [Table 1](#). However, readback CRC (POST\_CRC), which is typically used for SEU detection, is supported.

This issue will not be fixed in the devices listed in [Table 1](#).

#### **Work-around**

Use 18K block RAM if configuration readback will be used.

See [Answer Record 39977](#).

## SCD9951 Test Conditions

The devices listed in [Table 1](#) support the Industrial temperature range ( $T_j = -40^{\circ}\text{C}$  to  $+100^{\circ}\text{C}$ ), unless otherwise specified.

## Operational Guidelines

### ***Design Software Requirements***

The devices listed in [Table 1](#), unless otherwise specified, require the following Xilinx development software installation:

- Speed specification v1.08 (or later), Xilinx ISE Design Suite 12.1 (or later).

## Traceability

The XC6SLX45T is marked as shown in [Figure 1](#). The other devices in [Table 1](#) are marked similarly.




Figure 1: Example Device Top Mark

EN147\_01\_050610

## Additional Questions or Clarifications

For additional questions regarding these errata, contact Xilinx Technical Support: <http://www.xilinx.com/support/clearxpress/websupport.htm> or your Xilinx Sales Representative: <http://www.xilinx.com/company/contact.htm>.

## Revision History

Date	Version	Description
05/25/10	1.0	Initial Xilinx release under limited distribution.
06/16/10	1.0.1	Published to <a href="http://www.xilinx.com">http://www.xilinx.com</a> .
06/25/10	1.1	Removed the Spartan-6 LX4 device.
07/02/10	1.2	Added <a href="#">BPI Configuration Not Supported in LX25/T Device</a> .
03/18/11	1.3	Added <a href="#">IODELAY2</a> , <a href="#">9K Block RAM Initialization</a> , <a href="#">16-Bit SelectMAP Configuration Maximum CCLK Frequency for LX100/T Devices</a> , and <a href="#">Configuration Readback When Using 9K Block RAM</a> . Updated <a href="#">Dual Port Block RAM Address Overlap in READ_FIRST and Simple Dual Port Mode</a> .

## Notice of Disclaimer

ENGINEERING SAMPLE (ES) DEVICES ARE MADE AVAILABLE SOLELY FOR PURPOSES OF RESEARCH, DEVELOPMENT AND PROTOTYPING. ALL ES DEVICES ARE SOLD "AS-IS" WITH NO WARRANTY OF ANY KIND, EITHER EXPRESS OR IMPLIED. XILINX DOES NOT WARRANT THAT ES DEVICES ARE FULLY VERIFIED, TESTED, OR WILL OPERATE IN ACCORDANCE WITH DATA SHEET SPECIFICATIONS. XILINX DISCLAIMS ANY OBLIGATIONS FOR TECHNICAL SUPPORT AND BUG FIXES. XILINX SHALL NOT BE LIABLE FOR ANY DAMAGES, INCLUDING WITHOUT LIMITATION DIRECT, INDIRECT, INCIDENTAL, SPECIAL, RELIANCE, OR CONSEQUENTIAL DAMAGES ARISING FROM OR IN CONNECTION WITH THE USE OF ES DEVICES IN ANY MANNER WHATSOEVER, EVEN IF XILINX HAS BEEN ADVISED OF THE POSSIBILITY THEREOF. XILINX MAKES NO REPRESENTATION THAT ES DEVICES PROVIDE ANY PARTICULAR FUNCTIONALITY, OR THAT ES DEVICES WILL MEET THE REQUIREMENTS OF A PARTICULAR USER APPLICATION. XILINX DOES NOT WARRANT THAT ES DEVICES ARE ERROR-FREE, NOR DOES XILINX MAKE ANY OTHER REPRESENTATIONS OR WARRANTIES, WHETHER EXPRESS OR IMPLIED, STATUTORY OR OTHERWISE, INCLUDING, WITHOUT LIMITATION, IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, OR NON-INFRINGEMENT. THE FOREGOING STATES THE ENTIRE LIABILITY OF XILINX WITH RESPECT TO ES DEVICES.