



Power Supply Adapter Replacement On Certain Development Boards

XCN08015 (v1.0.1) May 23, 2008

Quality Alert

Overview

The purpose of this alert is to communicate to customers that some development board shipments included power plug or adapters that might not meet European Union requirements.

Description

The affected products, as listed below, were shipped with power cords fitted with plugs primarily used in North America ("NEMA" style) and included a separate plug-to-wall adapter. A replacement cord is available to customers who need a cord with a country-specific plug by contacting Xilinx at XCN08015@xilinx.com.

Xilinx has ceased shipment of the non-conforming configuration and new development board purchases are being shipped with cords fitted with appropriate plugs. This Quality Alert only applies to those products already shipped, see Traceability section.

Products Affected

Xilinx Part Numbers	
HW-SPAR3E-SK-EC	HW-V4-ML402-UNI-G
HW-SPAR3E-SK-EC-PROMO	HW-V4-ML403-UNI-G
HW-SPAR3E-SK-UK	DO-ML403-EDK-ISE-USB-UNI-G
HW-SPAR3E-SK-UK-PROMO	HW-V4-ML401-UK
HW-SPAR3E-SK-J	HW-V4-ML401-EC
HW-SPAR3E-SK-J-PROMO	HW-V4-ML402-UK
HW-SPAR3A-SK-UNI-G	HW-V4-ML402-EC
HW-SPAR3-SK-UNI-G	DO-ML403-EDK-ISE-USB-UK
HW-SPAR3ADDR2-DK-UNI-G	DO-ML403-EDK-ISE-PC4-UK
HW-SPAR3ADDR2-DK-UNI-G-PROMO1	DO-ML403-EDK-ISE-PC4-EC
HW-SPAR3AN-SK-UNI-G	DO-ML403-EDK-ISE-USB-EC
HW-SPAR3AN-SK-UNI-G-PROMO	DO-ML501-ISE-UNI-G
HW-SPAR3E-CPLD-SP-SK-UNI	HW-V4-ML405-UNI-G
HW-SPAR3E-SK-EC-G	HW-V4-ML423-UNI-G
HW-SPAR3E-SK-UK-G	HW-V5-ML521-UNI-G
DO-SP3E1600E-DK-UNI-G	HW-V5-ML523-UNI-G
DO-SP3E1600E-DK-UNI-G-COUPON	HW-V5-ML550-UNI-G
DO-SP3E1600E-DK-UNI-G-PROMO	HW-V5-ML561-UNI-G
HW-SPAR3E-SK-UNI-G	HW-SD3400A-DSP-DB-UNI-G
HW-V4-ML403-UK	DO-S3ADSP-VIDEO-SK-UNI-G
HW-V4-ML403-EC	HW-SPAR3E-DISP-DK-UNI-G
HW-V5-ML501-UNI-G	HW-SPAR3E-DISP-DK-UNI-G-PROMO
HW-V4-ML401-UNI-G	HW-MLX10-RACK-G
	HW-V4-ML410-UNI-G

XCN08015 (v1.0.1) May 23, 2008

www.xilinx.com

1

Traceability

The affected products include a two-blade NEMA plug and a separate cord-to-wall adapter, as shown in the figures below. The photos below are intended for reference and will not illustrate every configuration.




Figure 1: Example Non-compatible power supply adapter
(May not represent exact configuration in all cases)



Figure 2: Example New compatible power supply solution
(May not represent exact configuration in all cases)

Recommendations

If you believe that you have purchased a non-compatible power adapter or supply, please contact your Xilinx Sales team, or send an email to: XCN08015@xilinx.com to request a replacement power solution. Please identify the Xilinx part number listed in the Products Affected section of this alert in your email.

Please contact Xilinx for a replacement within 90 days of this notice.

Additional Documentation

None available.

Revision History

The following table shows the revision history for this document.

Date	Version	Revision
05/05/08	1.0	Initial release.
05/23/08	1.0.1	Minor editorial update; latest template.