

# Product Discontinuation Notice PDN2000-05

## Discontinuation of Certain HardWire 1 Products (1.0um and 1.5um)

---

**Subject:** Discontinuation of Certain HardWire 1 Products (1.0um and 1.5um)

**Products Affected:**

<b>Family</b>	<b>Package</b>	<b>Replacement Device (Family)</b>
XC2318	All	XC2018
XC3330	All	XC3030
XC3342	All	XC3042
XC3390	All	XC3090

**Change Description:** Xilinx is discontinuing the above product/package combinations.

**Reason For Change:** The above product/package combinations have declined in customer demand where manufacturing is no longer becoming economical. In order for Xilinx to continue the evolutionary process of cost reductions, it is necessary to discontinue these devices.

**Replacement Device:** Since the above devices are a subset of the HardWire 1 architecture, migration from the HardWire 1 design back to the replacement device is relatively straightforward. Please contact Reid Swanson ([reid.swanson@xilinx.com](mailto:reid.swanson@xilinx.com) or 408-879-6507) for assistance on replacement devices.

**Key Dates:**

Final orders accepted until November 30, 2000

Final deliveries on or before December 30, 2001

**Response:** No response to this notification is required. Please address any questions you may have via email at "[pcn@xilinx.com](mailto:pcn@xilinx.com)", or directly by fax at (408) 369-1718.