

PDN2000-07: Products Affected

Part Number	Last Time Buy	Last Time Ship	Philips Cross Reference
XCR22LV10-10PC28C	April 27, 2001	December 28, 2001	P3Z22V10-10A
XCR22LV10-10SO24C	April 27, 2001	December 28, 2001	P3Z22V10-10D
XCR22LV10-10VO24C	April 27, 2001	December 28, 2001	P3Z22V10-10DH
XCR22LV10-15PC28C	April 27, 2001	December 28, 2001	P3Z22V10-15A
XCR22LV10-15PC28I	April 27, 2001	December 28, 2001	P3Z22V10-15D
XCR22LV10-15SO24C	April 27, 2001	December 28, 2001	P3Z22V10-15DH
XCR22LV10-15SO24I	April 27, 2001	December 28, 2001	P3Z22V10I15A
XCR22LV10-15VO24C	April 27, 2001	December 28, 2001	P3Z22V10I15D
XCR22LV10-15VO24I	April 27, 2001	December 28, 2001	P3Z22V10I15DH
XCR22V10-10PC28C	April 27, 2001	December 28, 2001	P5Z22V10-10A
XCR22V10-10PC28I	April 27, 2001	December 28, 2001	P5Z22V10-10D
XCR22V10-10SO24C	April 27, 2001	December 28, 2001	P5Z22V10-10DH
XCR22V10-10SO24I	April 27, 2001	December 28, 2001	P5Z22V10I10A
XCR22V10-10VO24C	April 27, 2001	December 28, 2001	P5Z22V10I10D
XCR22V10-10VO24I	April 27, 2001	December 28, 2001	P5Z22V10I10DH
XCR22V10-7PC28C	April 27, 2001	December 28, 2001	P5Z22V10-7A
XCR22V10-7SO24C	April 27, 2001	December 28, 2001	P5Z22V10-7D
XCR22V10-7VO24C	April 27, 2001	December 28, 2001	P5Z22V10-7DH
XCR3032-10PC44C	April 27, 2001	December 28, 2001	PZ3032-10A44
XCR3032-10PC44I	April 27, 2001	December 28, 2001	PZ3032I10A44
XCR3032-10VQ44C	April 27, 2001	December 28, 2001	PZ3032-10BC
XCR3032-10VQ44I	April 27, 2001	December 28, 2001	PZ3032I10BC
XCR3032-12PC44C	April 27, 2001	December 28, 2001	PZ3032-12A44
XCR3032-12PC44I	April 27, 2001	December 28, 2001	PZ3032I12A44
XCR3032-12VQ44C	April 27, 2001	December 28, 2001	PZ3032-12BC
XCR3032-12VQ44I	April 27, 2001	December 28, 2001	PZ3032I12BC
XCR3032-8PC44C	April 27, 2001	December 28, 2001	PZ3032-8A44
XCR3032-8VQ44C	April 27, 2001	December 28, 2001	PZ3032-8BC
XCR3032A-10PC44C	April 27, 2001	December 28, 2001	PZ3032AS10A44

Part Number	Last Time Buy	Last Time Ship	Philips Cross Reference
XCR3032A-10PC44I	April 27, 2001	December 28, 2001	PZ3032DS10A44
XCR3032A-10VQ44C	April 27, 2001	December 28, 2001	PZ3032AS10BC
XCR3032A-10VQ44I	April 27, 2001	December 28, 2001	PZ3032DS10BC
XCR3032A-6PC44C	April 27, 2001	December 28, 2001	PZ3032AS6A44
XCR3032A-6VQ44C	April 27, 2001	December 28, 2001	PZ3032AS6BC
XCR3032A-7PC44C	April 27, 2001	December 28, 2001	PZ3032AS7A44
XCR3032A-7PC44I	April 27, 2001	December 28, 2001	PZ3032DS7A44
XCR3032A-7VQ44C	April 27, 2001	December 28, 2001	PZ3032AS7BC
XCR3032A-7VQ44I	April 27, 2001	December 28, 2001	PZ3032DS7BC
XCR3032C-10PC44C	April 27, 2001	December 28, 2001	PZ3032CS10A44
XCR3032C-10PC44I	April 27, 2001	December 28, 2001	PZ3032NS10A44
XCR3032C-10VQ44C	April 27, 2001	December 28, 2001	PZ3032CS10BC
XCR3032C-10VQ44I	April 27, 2001	December 28, 2001	PZ3032NS10BC
XCR3032C-12PC44C	April 27, 2001	December 28, 2001	PZ3032CS12A44
XCR3032C-12PC44I	April 27, 2001	December 28, 2001	PZ3032NS12A44
XCR3032C-12VQ44C	April 27, 2001	December 28, 2001	PZ3032CS12BC
XCR3032C-12VQ44I	April 27, 2001	December 28, 2001	PZ3032NS12BC
XCR3032C-8PC44C	April 27, 2001	December 28, 2001	PZ3032CS8A44
XCR3032C-8VQ44C	April 27, 2001	December 28, 2001	PZ3032CS8BC
XCR3064-10PC44C	April 27, 2001	December 28, 2001	PZ3064-10A44
XCR3064-10PC68C	April 27, 2001	December 28, 2001	PZ3064-10A68
XCR3064-10PC84C	April 27, 2001	December 28, 2001	PZ3064-10A84
XCR3064-10PQ100C	April 27, 2001	December 28, 2001	PZ3064-10BB1
XCR3064-10VQ44C	April 27, 2001	December 28, 2001	PZ3064-10BC
XCR3064-12PC44C	April 27, 2001	December 28, 2001	PZ3064-12A44
XCR3064-12PC44I	April 27, 2001	December 28, 2001	PZ3064I12A44
XCR3064-12PC68C	April 27, 2001	December 28, 2001	PZ3064-12A68
XCR3064-12PC68I	April 27, 2001	December 28, 2001	PZ3064I12A68
XCR3064-12PC84C	April 27, 2001	December 28, 2001	PZ3064-12A68
XCR3064-12PC84I	April 27, 2001	December 28, 2001	PZ3064I12A68
XCR3064-12PQ100C	April 27, 2001	December 28, 2001	PZ3064-12BB1
XCR3064-12PQ100I	April 27, 2001	December 28, 2001	PZ3064I12BB1
XCR3064-12VQ44C	April 27, 2001	December 28, 2001	PZ3064-12BC

Part Number	Last Time Buy	Last Time Ship	Philips Cross Reference
XCR3064-12VQ44I	April 27, 2001	December 28, 2001	PZ3064I12BC
XCR3064-15PC44I	April 27, 2001	December 28, 2001	PZ3064I15A44
XCR3064-15PC68I	April 27, 2001	December 28, 2001	PZ3064I15A68
XCR3064-15PC84I	April 27, 2001	December 28, 2001	PZ3064I15A84
XCR3064-15PQ100I	April 27, 2001	December 28, 2001	PZ3064I15BB1
XCR3064-15VQ44I	April 27, 2001	December 28, 2001	PZ3064I15BC
XCR3064A-10CP56C	April 27, 2001	December 28, 2001	PZ3064AS10EC
XCR3064A-10CP56I	April 27, 2001	December 28, 2001	PZ3064DS10EC
XCR3064A-10PC44C	April 27, 2001	December 28, 2001	PZ3064AS10A44
XCR3064A-10PC44I	April 27, 2001	December 28, 2001	PZ3064DS10A44
XCR3064A-10VQ100C	April 27, 2001	December 28, 2001	PZ3064AS10BP
XCR3064A-10VQ100I	April 27, 2001	December 28, 2001	PZ3064DS10BP
XCR3064A-10VQ44C	April 27, 2001	December 28, 2001	PZ3064AS10BC
XCR3064A-10VQ44I	April 27, 2001	December 28, 2001	PZ3064DS10BC
XCR3064A-12CP56I	April 27, 2001	December 28, 2001	PZ3064DS12EC
XCR3064A-12PC44I	April 27, 2001	December 28, 2001	PZ3064DS12A44
XCR3064A-12VQ100I	April 27, 2001	December 28, 2001	PZ3064DS12BP
XCR3064A-12VQ44I	April 27, 2001	December 28, 2001	PZ3064DS12BC
XCR3064A-7CP56C	April 27, 2001	December 28, 2001	PZ3064AS7EC
XCR3064A-7PC44C	April 27, 2001	December 28, 2001	PZ3064AS7A44
XCR3064A-7VQ100C	April 27, 2001	December 28, 2001	PZ3064AS10BP
XCR3064A-7VQ44C	April 27, 2001	December 28, 2001	PZ3064AS7BC
XCR3128-DIE	April 27, 2001	December 28, 2001	XPZ3128CU
XCR3128-10PC84C	April 27, 2001	December 28, 2001	PZ3128-S10A84
XCR3128-10PQ100C	April 27, 2001	December 28, 2001	PZ3128-S10BB1
XCR3128-10PQ160C	April 27, 2001	December 28, 2001	PZ3128-S10BB2
XCR3128-10TQ128C	April 27, 2001	December 28, 2001	PZ3128-S10BE
XCR3128-10VQ100C	April 27, 2001	December 28, 2001	PZ3128-S10BP
XCR3128-12PC84C	April 27, 2001	December 28, 2001	PZ3128-S12A84
XCR3128-12PC84I	April 27, 2001	December 28, 2001	PZ3128IS12A84
XCR3128-12PQ100C	April 27, 2001	December 28, 2001	PZ3128-S12BB1
XCR3128-12PQ100I	April 27, 2001	December 28, 2001	PZ3128IS12BB1
XCR3128-12PQ160C	April 27, 2001	December 28, 2001	PZ3128-S12BB2

Part Number	Last Time Buy	Last Time Ship	Philips Cross Reference
XCR3128-12PQ160I	April 27, 2001	December 28, 2001	PZ3128IS12BB2
XCR3128-12TQ128C	April 27, 2001	December 28, 2001	PZ3128-S12BE
XCR3128-12TQ128I	April 27, 2001	December 28, 2001	PZ3128IS12BE
XCR3128-12VQ100C	April 27, 2001	December 28, 2001	PZ3128-S12BP
XCR3128-12VQ100I	April 27, 2001	December 28, 2001	PZ3128IS12BP
XCR3128-15PC84C	April 27, 2001	December 28, 2001	PZ3128-S15A84
XCR3128-15PC84I	April 27, 2001	December 28, 2001	PZ3128IS15A84
XCR3128-15PQ100C	April 27, 2001	December 28, 2001	PZ3128-S15BB1
XCR3128-15PQ100I	April 27, 2001	December 28, 2001	PZ3128IS15BB1
XCR3128-15PQ160C	April 27, 2001	December 28, 2001	PZ3128-S15BB2
XCR3128-15PQ160I	April 27, 2001	December 28, 2001	PZ3128IS15BB2
XCR3128-15TQ128C	April 27, 2001	December 28, 2001	PZ3128-S15BE
XCR3128-15TQ128I	April 27, 2001	December 28, 2001	PZ3128IS15BE
XCR3128-15VQ100C	April 27, 2001	December 28, 2001	PZ3128-S15BP
XCR3128-15VQ100I	April 27, 2001	December 28, 2001	PZ3128IS15BP
XCR3128A-10TQ128C	April 27, 2001	December 28, 2001	PZ3128AS10BE
XCR3128A-10TQ128I	April 27, 2001	December 28, 2001	PZ3128DS10BE
XCR3128A-10VQ100C	April 27, 2001	December 28, 2001	PZ3128AS10BP
XCR3128A-10VQ100I	April 27, 2001	December 28, 2001	PZ3128DS10BP
XCR3128A-12TQ128C	April 27, 2001	December 28, 2001	PZ3128AS12BE
XCR3128A-12VQ100C	April 27, 2001	December 28, 2001	PZ3128AS12BP
XCR3128A-15TQ128I	April 27, 2001	December 28, 2001	PZ3128DS15BE
XCR3128A-15VQ100I	April 27, 2001	December 28, 2001	PZ3128DS15BP
XCR3128A-7TQ128C	April 27, 2001	December 28, 2001	PZ3128AS7BE
XCR3128A-7VQ100C	April 27, 2001	December 28, 2001	PZ3128AS7BP
XCR3320-10BG256C	April 27, 2001	December 28, 2001	PZ3320C10EB
XCR3320-10TQ160C	April 27, 2001	December 28, 2001	PZ3320C10BE
XCR3320-7BG256C	April 27, 2001	December 28, 2001	PZ3320C7EB
XCR3320-7TQ160C	April 27, 2001	December 28, 2001	PZ3320C7BE
XCR3320-8BG256I	April 27, 2001	December 28, 2001	PZ3320N8EB
XCR3320-8TQ160I	April 27, 2001	December 28, 2001	PZ3320N8BE
XCR3960-7BG492C	April 27, 2001	December 28, 2001	PZ3960C7EB
XCR3960-8BG492I	April 27, 2001	December 28, 2001	PZ3960N8EB

Part Number	Last Time Buy	Last Time Ship	Philips Cross Reference
XCR5032-10PC44C	April 27, 2001	December 28, 2001	PZ5032-10A44
XCR5032-10PC44I	April 27, 2001	December 28, 2001	PZ5032I10A44
XCR5032-10VQ44C	April 27, 2001	December 28, 2001	PZ5032-10BC
XCR5032-10VQ44I	April 27, 2001	December 28, 2001	PZ5032I10BC
XCR5032-6PC44C	April 27, 2001	December 28, 2001	PZ5032-6A44
XCR5032-6VQ44C	April 27, 2001	December 28, 2001	PZ5032-6BC
XCR5032-7PC44C	April 27, 2001	December 28, 2001	PZ5032-7A44
XCR5032-7PC44I	April 27, 2001	December 28, 2001	PZ5032I7A44
XCR5032-7VQ44C	April 27, 2001	December 28, 2001	PZ5032-7BC
XCR5032-7VQ44I	April 27, 2001	December 28, 2001	PZ5032I7BC
XCR5032C-10PC44C	April 27, 2001	December 28, 2001	PZ5032CS10A44
XCR5032C-10PC44I	April 27, 2001	December 28, 2001	PZ5032NS10A44
XCR5032C-10VQ44C	April 27, 2001	December 28, 2001	PZ5032CS10BC
XCR5032C-10VQ44I	April 27, 2001	December 28, 2001	PZ5032NS10BC
XCR5032C-6PC44C	April 27, 2001	December 28, 2001	PZ5032CS6A44
XCR5032C-6VQ44C	April 27, 2001	December 28, 2001	PZ5032CS6BC
XCR5032C-7PC44C	April 27, 2001	December 28, 2001	PZ5032CS7A44
XCR5032C-7PC44I	April 27, 2001	December 28, 2001	PZ5032NS7A44
XCR5032C-7VQ44C	April 27, 2001	December 28, 2001	PZ5032CS7BC
XCR5032C-7VQ44I	April 27, 2001	December 28, 2001	PZ5032NS7BC
XCR5064-10PC44C	April 27, 2001	December 28, 2001	PZ5064-10A44
XCR5064-10PC44I	April 27, 2001	December 28, 2001	PZ5064I10A44
XCR5064-10PC68C	April 27, 2001	December 28, 2001	PZ5064-10A68
XCR5064-10PC68I	April 27, 2001	December 28, 2001	PZ5064I10A68
XCR5064-10PC84C	April 27, 2001	December 28, 2001	PZ5064-10PC84
XCR5064-10PC84I	April 27, 2001	December 28, 2001	PZ5064I10PC84
XCR5064-10PQ100C	April 27, 2001	December 28, 2001	PZ5064-10BB1
XCR5064-10PQ100I	April 27, 2001	December 28, 2001	PZ5064I10BB1
XCR5064-10VQ44C	April 27, 2001	December 28, 2001	PZ5064-10BC
XCR5064-10VQ44I	April 27, 2001	December 28, 2001	PZ5064I10BC
XCR5064-12PC44I	April 27, 2001	December 28, 2001	PZ5064I12A44
XCR5064-12PC68I	April 27, 2001	December 28, 2001	PZ5064I12A68
XCR5064-12PC84I	April 27, 2001	December 28, 2001	PZ5064I12A84

Part Number	Last Time Buy	Last Time Ship	Philips Cross Reference
XCR5064-12PQ100I	April 27, 2001	December 28, 2001	PZ5064I12BB1
XCR5064-12VQ44I	April 27, 2001	December 28, 2001	PZ5064I12BC
XCR5064-7PC44C	April 27, 2001	December 28, 2001	PZ5064-7A44
XCR5064-7PC68C	April 27, 2001	December 28, 2001	PZ5064-7A68
XCR5064-7PC84C	April 27, 2001	December 28, 2001	PZ5064-7A84
XCR5064-7PQ100C	April 27, 2001	December 28, 2001	PZ5064-7BB1
XCR5064-7VQ44C	April 27, 2001	December 28, 2001	PZ5064-7BC
XCR5064C-10PC44C	April 27, 2001	December 28, 2001	PZ5064CS10A44
XCR5064C-10PC44I	April 27, 2001	December 28, 2001	PZ5064NS10A44
XCR5064C-10VQ100C	April 27, 2001	December 28, 2001	PZ5064CS10BP
XCR5064C-10VQ100I	April 27, 2001	December 28, 2001	PZ5064NS10BP
XCR5064C-10VQ44C	April 27, 2001	December 28, 2001	PZ5064CS10BC
XCR5064C-10VQ44I	April 27, 2001	December 28, 2001	PZ5064NS10BC
XCR5064C-12PC44I	April 27, 2001	December 28, 2001	PZ5064NS12A44
XCR5064C-12VQ100I	April 27, 2001	December 28, 2001	PZ5064NS12BP
XCR5064C-12VQ44I	April 27, 2001	December 28, 2001	PZ5064NS12BC
XCR5064C-7PC44C	April 27, 2001	December 28, 2001	PZ5064CS7A44
XCR5064C-7VQ100C	April 27, 2001	December 28, 2001	PZ5064CS7BP
XCR5064C-7VQ44C	April 27, 2001	December 28, 2001	PZ5064CS7BC
XCR5128-10PC84C	April 27, 2001	December 28, 2001	PZ5128-S10A84
XCR5128-10PC84I	April 27, 2001	December 28, 2001	PZ5128IS10A84
XCR5128-10PQ100C	April 27, 2001	December 28, 2001	PZ5128-S10BB1
XCR5128-10PQ100I	April 27, 2001	December 28, 2001	PZ5128IS10BB1
XCR5128-10PQ160C	April 27, 2001	December 28, 2001	PZ5128-S10BB2
XCR5128-10PQ160I	April 27, 2001	December 28, 2001	PZ5128IS10BB2
XCR5128-10TQ128C	April 27, 2001	December 28, 2001	PZ5128-S10BE
XCR5128-10TQ128I	April 27, 2001	December 28, 2001	PZ5128IS10BE
XCR5128-10VQ100C	April 27, 2001	December 28, 2001	PZ5128-S10BP
XCR5128-10VQ100I	April 27, 2001	December 28, 2001	PZ5128IS10BP
XCR5128-12PC84C	April 27, 2001	December 28, 2001	PZ5128-S12A84
XCR5128-12PQ100C	April 27, 2001	December 28, 2001	PZ5128-S12BB1
XCR5128-12PQ160C	April 27, 2001	December 28, 2001	PZ5128-S12BB2
XCR5128-12TQ128C	April 27, 2001	December 28, 2001	PZ5128-S12BE

Part Number	Last Time Buy	Last Time Ship	Philips Cross Reference
XCR5128-12VQ100C	April 27, 2001	December 28, 2001	PZ5128-S12BP
XCR5128-15PC84I	April 27, 2001	December 28, 2001	PZ5128IS15A84
XCR5128-15PQ100I	April 27, 2001	December 28, 2001	PZ5128IS15BB1
XCR5128-15PQ160I	April 27, 2001	December 28, 2001	PZ5128IS15BB2
XCR5128-15TQ128I	April 27, 2001	December 28, 2001	PZ5128IS15BE
XCR5128-15VQ100I	April 27, 2001	December 28, 2001	PZ5128IS15BP
XCR5128-7PC84C	April 27, 2001	December 28, 2001	PZ5128-S7A84
XCR5128-7PQ100C	April 27, 2001	December 28, 2001	PZ5128-S7BB1
XCR5128-7PQ160C	April 27, 2001	December 28, 2001	PZ5128-S7BB2
XCR5128-7TQ128C	April 27, 2001	December 28, 2001	PZ5128-S7BE
XCR5128-7VQ100C	April 27, 2001	December 28, 2001	PZ5128-S7BP
XCR5128C-10TQ128C	April 27, 2001	December 28, 2001	PZ5128CS10BE
XCR5128C-10TQ128I	April 27, 2001	December 28, 2001	PZ5128NS10BE
XCR5128C-10VQ100C	April 27, 2001	December 28, 2001	PZ5128CS10BP
XCR5128C-10VQ100I	April 27, 2001	December 28, 2001	PZ5128NS10BP
XCR5128C-12TQ128C	April 27, 2001	December 28, 2001	PZ5128CS12BE
XCR5128C-12VQ100C	April 27, 2001	December 28, 2001	PZ5128CS12BP
XCR5128C-15TQ128I	April 27, 2001	December 28, 2001	PZ5128NS15BE
XCR5128C-15VQ100I	April 27, 2001	December 28, 2001	PZ5128NS15BP
XCR5128C-7TQ128C	April 27, 2001	December 28, 2001	PZ5128CS7BE
XCR5128C-7VQ100C	April 27, 2001	December 28, 2001	PZ5128CS7BP